



June 9, 2023

ADDENDUM NO. 01
Invitation for Bid 23-15
Eaton 9355-20-30 UPS Battery Replacement and Tray Upgrade

Prospective Proposers and all concerned are hereby notified of the following changes/comments related to the Invitation for Bids (IFB) document 23-15. These changes/comments shall be incorporated in and shall become an integral part of the IFB.

Below are questions posed by Prospective Proposers along with RITBA's response:

- How many of the new battery trays, P-106000220, are needed? ***Full Internal Battery Replacement, (kit including 2 battery trays, 9 batteries per tray) 108 batteries, 12 trays. It is the Contractors responsibility to verify the tray and battery count using the supplied model number and serial number. RITBA will not be responsible for any errors in the estimate provided.***
- Is there a loading dock for delivery of the new batteries? ***No, but a forklift is available for tailgate unload.***
- Is there room to store the batteries on site? ***Yes, in the Maintenance garage.***
- Is this UPS on the first floor? If not, is there an elevator available for use? ***Yes, Server room is located on the ground level.***
- How far is the UPS from the loading dock or elevator? ***Short distance. Forklift or pallet jack can relocate batteries.***
- Remove and replace all batteries in an Eaton UPS model number 9355-20-30. What is the quantity and model size of the existing battery? ***Full Internal Battery Replacement, (kit including 2 battery trays, 9 batteries per tray) 108 batteries, 12 trays. Battery model PWHR1234W2FR, float voltage 13.5-13.8V, 34 watts per cell. It is the Contractors responsibility to verify the tray and battery count using the supplied model number and serial number. RITBA will not be responsible for any errors in the estimate provided.***
- Batteries must be equivalent type to manufactures original. What is an acceptable alternative manufacturer for the battery? ***Any manufacture matching the same specification and quality (VRLA Sealed). Battery model PWHR1234W2FR, float voltage 13.5-13.8V, 34 watts per cell.***
- Upgrade the discontinued trays (P/N: P-103000933, revision 5) to upgrade kit P106000220 which includes two row battery assembly and two harness adapters. What is the quantity of battery trays to replace? ***Full Internal Battery Replacement, (kit including 2 battery trays, 9 batteries per tray) 108 batteries, 12 trays. It is the Contractors responsibility to verify the tray and battery count using the supplied model number and serial number. RITBA***

will not be responsible for any errors in the estimate provided.

- Are there any access issues from the street or parking to the battery location? IE stairs, elevators, small doorways. **No**
- Will the battery and battery trays be delivered to the location, or should we plan on transporting the new parts to the location? ***The successful contractor can plan to have supplies delivered directly to the facility.***
- What will be the times acceptable for the battery removal/replacement? Monday to Friday 7:00AM to 5:00PM or after business hours or weekends? ***RITBA will require the service to be performed after 6:00 PM Monday through Friday or during the day on weekends.***

###END OF ADDENDUM###